

C. N. R. OFFICIAL TRAIN MEETS WITH ACCIDENT

Unpleasant Occurrence Mars Opening of the New Line
to Trenton—Engine Turned on Its Side—Fortunately No One Was Injured.

Grafton, Oct. 3.—The opening of the new Canadian Northern line from Toronto to Trenton today was marred by an accident near Grafton, in which, however, no person was hurt. Owing to a "split switch," which passed through several cars, one left half open train No. 7, which left Trenton at 4 o'clock this morning, left the rails. The engine stopped over on its side on the south side of the track. The tender was left standing on the track, and the engineers car went across the north end of the track.

About twenty passengers in all were on the train, including a party of Canadian Northern officials and a number of pressmen. The engineer, C. W. Wilcox, the fender was probably the main cause of the accident. He was thrown right out of the seat. He did not sustain a fracture and escaped

with hardly a bruise. Engineer Moore managed to hold the seat throughout the first震撼, but the passengers had to scramble upward. A severe jolt. Many of them were thrown from their seats, including Mr. D. B. Brown, Third Vice-President of the C. N. R., but none of them was hurt. The train was made up of three passenger cars, a dinner and two first-class coaches. It was traveling about twenty miles an hour when the accident happened at a point half a mile east of Grafton station. Conductor Fred Russell said that the conductor was due to the switch having sprung, which resulted in the train being scattered from some one having happened with it. It happened at 1:15 o'clock.

The free train, which left Trenton at 7 o'clock this morning, returned as far as Grafton this evening and conveyed the passengers back to Trenton, where they did not arrive until long after midnight, whereas they were due at 1:30 o'clock.

October 10

1911

No to Trenton