**CANADIAN NATIONAL** RAILWAYS WRECK CALLANDAR **AUGUST** 1930

## W

todi

BCT

# TRAIN JUMPS TRACK, JU KILLING ENGINEER, No INJURING FIREMAN

Engine and Five Passenger Coaches Leave Rails Near Callander

## SURVIVOR LAUDS VICTIM

(Special Despatch to The Globe.)

North Bay, Aug. 4.—Engineer William Hill, 52 years old, of Allandale, died this morning while en route here by special train from the wreck of the Canadian National all-steel passenger train No. 47, en route north from Toronto to North Bay. The engine and five coaches left the tracks. Harry Tomlin, fireman, siso of Allandale, is a patient at the Queen Victoria Memorial Hospital, North Bay, suffering from burns caused by escaping steam. His condition, according to Dr. W. G. Smith, is good and he will recover.

The accident occurred when the train spex was seven and a half miles south of gion Callender at 5.50 o'clock and running Boss on time. Aithough no official announcement has been made, it is believed were that a spread rail was the cause.

"Did His Duty."

Interviewed at the Queen Victoria Memorial Hospital, Pireman Tomilin said: "It all happened so suddenly. Hill did his duty. He was running as spare engineer. Edward Ayres was the regular engineer for the run, but he was off for this trip. When the accident occurred Hill put on the brakes, and as the steam gushed out upon his body he said "Save my mate." How thoughtful of him!

"I don't know what caused the accident. I got out myself through the window on my side of the partly over-turned engine. It was tough to think that we could not rescue him because of the steam."

Auxiliary equipment was rushed from North Bay and Allandale Di-

(Continued on Page 2, Col. 4.)

selli
the
A
over
ber
at 1
Ren
August 4

1930

Boas The Globe

CNR Callander

I.

bush

lang

supp

Droi

a

- -- while it is believed that death occurred this afternoon. An inquest will probably be held Wednesday.

# TRAIN JUMPS TRACK, KILLING ENGINEER

(Continued from Page 1, Column 1) visions, and it was expected that the tracks would be cleared before night and traffic resumed. The mail car, next an to the engine left the track. In it were four mail cirries N McClure, in charge, ald and Robert McGuffin. Harry the and Morley Anderson, all of Toronto The express baggage second class and first class day coaches also left the track, but no one was injured

A transfer passenger train arrived at the station at noon, among the passengers being Miss Lillian Day, Mr. and Mrs C Pratt and daughters, Ivy and Vera of North Bay, who have been on visiting in Toronto, and Judge H. D. Leark, North Bay Conductor Condy, Allandale was in charge The sleeping to cars did not leave the tracks, which were ripped up for about four car lengths

### Father of Six

200 E

363 27

lay ent di-

xts

Engineer Hill was married and leaves six children Mrs L. Emms and Mrs. P Lowe Barrie, Mrs E Irwin, Toronto. and William, Harold and Leola, at home Leola who is 13 years old, has for the past ten days beech visiting relatives in North Bay, Mr and Mrs. J N Bradford, 36 Metcalfe Street Mr. Emma and Harold Hill arrived here to-)- day by automobile and will complete funeral arrangements

A northbound freight train passed over the ratis about an hour before the WIFCE

#### C.N.R. Statement.

W A Kingsland, General Manager Central Region, Canadian National Railways, issued the following statement concerning the detailment of train No 47 at Mile 98.75, south of Hills Huntsville Subdivision, Aug 4

"Train No. 47 en route Toronto to North Bay had engine 3332, tender and four head-end cars detailed at Miles ed as 9873 about our mile south of Hills. Runtaville Subdivision, 5.55 a.m. Aug 4. The five rear and sleeping cars remained on the track. None of the passengers were injured. The cause of the accident has not been determined and | guise is being thoroughly investigated Immediately the accident was reported auxiliaries were despatched from North ar and Allandale Engineer W Hill of Allandale was so severely scaled that he died of his injuries at \$45 am. d while being rushed to North Bay by special train Pireman R Tomlin, of Allandale also, had his arms and legs badly scalded, and was taken to the hospital at North Bay, where it is reported he will recover J. Snodden, express messenger sustained bruises about the face. The injured men were attended by the company's medical officera."

Bridegroom's Furniture Is Burned on Truck August 4

The Globe

CWR Callendar

Tha tur accox

matel

Yarr

most.

IC

C.N.R. Statement.

W A Kingsland General Manager Central Region Canadian National Railways issued the following statement concerning the detailment of train No 42 at Mile 98.75, south of Hills Huntsville Subdivision Aug 4

"Train No 47 en route Toronto to North Bay had engine 3332, tender and four head-end cars derailed at Miley 98.75 about one mile south of Hills, Huntsville Subdivision, 5.55 a.m. Aug. 4. The five rear and sleeping cars remained on the track. None of the passengers were injured. The cause of the accident has not been determined and is being thoroughly investigated Immediately the accident was reported auxiliaries were despatched from North Bar and Allandale Engineer W Hill of Chandale was so severely scalded that he died of his injuries at 845; a.m. thile being rushed to North Hay by pecial train Fireman H Tomilio, of Illandale also, had his arms and legs adly scalded and was taken to the iospital at North Bay, where it is reorted he will recover J Snodden, exress messenger sustained bruises about he face. The injured men were attendd by the company's medical officers."

ridegroom's Furniture
Is Burned on Truck

August 4