HULL ELECTRIC



Details of Railway Accidents in the Ottawa Area

1897 July 7 Collision between a Hull Electric freight train and a passenger train at Aylmer

Ottawa Journal 7 July 1897: A freight train on the Hull Electric Co.'s track drawn by electric motor No. 1 ran into a passenger car filled with picknickers from Bank street Presbyterian church Sunday school bound for Queen's Park, Aylmer this forenoon. The accident took place at the "Y: near Aylmer station. The motor crushed in the end of passenger car No. 15. Mrs. James Dalglish of Slater street was sitting in the centre of the car and received injuries, chiefly about the knees, but not serious. All others escaped unharmed. The motor was derailed.

Also in the Shawville Equity, July 17.

Return to Main Page of Railway Accidents

Updated January 2014



Details of Railway Accidents in the Ottawa Area

1945, April 3 - A Hull Electric tramcar hits a washout on the approach to Ottawa station

Ottawa Citizen 3 April 1945

A fast moving Hull Electric Railway tram car carried 50 charwomen and its motorman safely over 35-foot section of unsupported track 100 feet above the swollen waters of the Ottawa river at 5.30 this morning after a wash-out during the night carried away a portion of a 40-foot-high retaining wall and sent it rolling into the river below.

First local car over the line, the tram was a special used for transporting members of the government char service to their work in offices in Ottawa. About an hour and a half earlier, a heavy CPR train, eastbound from Vancouver, passed over the section and railwaymen believe its tremendous weight may have caused the wall, weakened by water seepage and frost, to give way.

Motorman H. Holt of the Hull line said that midway across the weakened track his car tilted to a dangerous degree over the edge of the cliff, which drops 40 feet to a slope which angles about 60 feet to the water's edge.

Thought car derailed.

Fortunately for the motorman and his passengers the unsupported steel rails held firmly and the car passed safely to solid ground. There have been two derailments in the area in recent weeks and at first the motorman believed that this was what caused his car to lurch dangerously. It was not until he had brought the tram to a stop and walked back to investigate that he saw the yawning gap over which the car had passed and the proximity of the cliff's edge over which the tram might have rolled had it tilted any further.

The washout did not affect the CPR transcontinental main line tracks which adjoin the Hull Electric's road. The network of rails are embedded in a rocky ledge skirting the base of Major's Hill Park. Freight and passenger locomotives of the CPR were able to proceed on regular scheduled runs at slow speed over the weakened section of track.

The break occurred about half way between the Hull electric terminal at the Chateau Laurier and the Alexandria bridge.

Motorman Holt brought his passengers safely into the terminal and then notified his company and the CPR, owners of the right of way.

Start Temporary Wall

Section Foreman Joseph Belisle, 208 Redempteur street, Hull, responded with a crew of CPR workmen who began the work of clearing away the tons of rocky debris and the construction of a temporary wooden retaining wall. A crane was sent from Smiths Falls this afternoon to assist in the work.

The Hull Electric Company put a shuttle service into operation on its east track during the morning to maintain a makeshift service until the west track can be put into operation again.

1 of 3

Normal service over the area is not expected to be resumed until tomorrow, however, when the temporary retaining wall should be in place and the gap filled with crushed stone. The retaining wall bordering the right of way was erected some 45 years ago of heavy cut stone, some as large as two feet square, Some of these lurched and thundered down the cliffside to the edge of the river far below, tearing trees from their path and leaving deep gouges in the soft soil of the 60 foot slope.

A detailed inspection of the scene revealed that a small underground stream flowing from the high ground of Major's Hill Park some 40 feet above the level of the tracks, had over a period of years undermined the retaining wall. This, together with the almost constant vibration of Hull Electric trams and the heavier CPR trains passing over the right of way, weakened the structure sufficiently to cause it to give way.

The wall is about one-half mile long and will be thoroughly inspected for further signs of stress, officials said.

Return to Main Page of Railway Accidents

Updated January 2014

2 of 3 8/15/2016 5:29 PM

GRAND RIVER RAILWAY.

Grand River Ry. Co.—Lake

ungstown.

Eric and Northern Rv. Co.

ag The annual meetings of shareholders of the Grand River Ry, Co, and the Lake Eric and Northern Ry, Co, were held in Ţ. Mentreal, April 13, with H. J. Humphrey, Vice President, Eastern Lines, C.P.R., and President of both the Grand River Ry. Co. and Lake Eric and Northern Ry. Co., presiding. Reports for 1942 recorded that gress carnings of both companies had increased considerably. and that net excurres had improved in satisfactory manner ever those of 1941. Further increase in truffic during 1943 is anticipated. Grand River Ry. Co. directors were elected as follows: -W. M. Neal, Vice President, C.P.R.; E. P. Flintoft, K.C. Vice President and General Counsel, άľ. C.P.R.: Mr. Humphreyt L. L. Lang.
Kitchener, Cat.: J. E. Frowde Seagram.
Waterloo. Oat.: George Stephen, Vice
President. Traffle, C.P.R., and G. A.
Walker, K.C., General Solicitor, C.P.R.
The following Lake Eric and Northern
Br. Co. directors 3.27 25, ire: Ry. Co. directors were elected:—Mr. Neal; Col. Henry Cockshutt, Brantford, Ont.; George A. Dobbie, Galt, Ont.; Mr. Fintest: Mr. Humphrey; H. L. McCulioch, Galt; Mr. Stephen. Directors' meetings were held prior to and following the annual general meetings. Mr. Humphrey was re-elected President of bath companies.



Details of Railway Accidents in the Ottawa Area

1897 July 7 Collision between a Hull Electric freight train and a passenger train at Aylmer

Ottawa Journal 7 July 1897: A freight train on the Hull Electric Co.'s track drawn by electric motor No. 1 ran into a passenger car filled with picknickers from Bank street Presbyterian church Sunday school bound for Queen's Park, Aylmer this forenoon. The accident took place at the "Y: near Aylmer station. The motor crushed in the end of passenger car No. 15. Mrs. James Dalglish of Slater street was sitting in the centre of the car and received injuries, chiefly about the knees, but not serious. All others escaped unharmed. The motor was derailed.

Also in the Shawville Equity, July 17.

Return to Main Page of Railway Accidents

Updated January 2014